

U.S. Department
of Transportation

800 Independence Ave., S.W.
Washington, D.C. 20591

**Federal Aviation
Administration**

Transmittal Letter 16-06

JANUARY 29, 2016

**PREPARED BY THE AERONAUTICAL INFORMATION GROUP, AJV-53
(AVAILABLE ON THE WEB AT [HTTP://NFDC.FAA.GOV](http://NFDC.FAA.GOV))**

**The enclosed Standard Instrument Approach Procedures, Departure
Procedures/Takeoff Minimums and Fix Actions are effective as indicated.**

By amending: §97.23 VOR, VOR/DME, VOR or TACAN, and VOR/DME or TACAN; §97.25 LOC, LOC/DME,
LDA, LDA/DME, SDF, SDF/DME; §97.27 NDB, NDB/DME; §97.29 ILS, ILS/DME, MLS, MLS/DME,
MLS/RNAV; §97.31 RADAR SIAPs; §97.33 RNAV SIAPs; and §97.35 COPTER SIAPs, Identified as follows:
.....EFFECTIVE UPON PUBLICATION

AIRAC DATE	STATE	CITY	AIRPORT	FDC NUMBER	FDC DATE	SUBJECT
3-Mar-16	NJ	Vincentown	Red Lion	5/0277	01/19/16	RNAV (GPS) RWY 5, Orig

EFFECTIVE 3 MARCH 2016

FDC **5/0277** N73 IAP RED LION, VINCENTOWN, NJ. RNAV (GPS) RWY 5,
ORIG... CHART NOTE: PROCEDURE NA AT NIGHT. CHART NOTE:
HELICOPTER VISIBILITY REDUCTION BELOW 1 SM NOT AUTHORIZED.
CHART PROFILE NOTE: VISUAL SEGMENT - OBSTACLES. DELETE
DESCENT ANGLE 3.04/TCH 40. 34:1 IS NOT CLEAR. DELETE PROFILE
NOTE: VGSI AND DESCENT ANGLES NOT COINCIDENT. CHART MOUNT
HOLLY ASOS. THIS IS RNAV (GPS) RWY 5, ORIG-A. 1512212118-PERM